



## LD CD4X INSTRUCTIONS

95-1713


1. SECURE CROSSBAR TO JUNCTION BOX (PROVIDED BY OTHERS)



2. MAKE WIRING CONNECTIONS BETWEEN CORD AND JUNCTION BOX
3. ATTACH CANOPY COVER USING (2) KNOBS



4. ATTACH AC CABLES FROM CANOPY TO GRIPPERS ON TOP HAT OF EMITTER PLATE.



**WARNING:** Be certain all power is OFF! Wire according to local and national codes. This product should be installed by a qualified electrician.